

~~SECRET~~

1963 AUG 5 23 06Z

PRIORITY

OUT 51622

P 052239Z

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUCVAB/4080TH STRAT WG, OL 19, BARKSDALE AFB, LA

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUWBCR/15TH AF, MARCH AFB RIVERSIDE CAL.

RUWGAA/2D RTS BARKSDALE AFB, LA.

DA GRNC

BT

SECRET

CITE CIA-Z-801

6 AUG 1963

HFS

CJS

CFC

DMS

AOL

Grace (File)


15TH AF (FOR DM4); SAC (FOR DIM, BRASS KNOB, DOCR, DM4). FROM
NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 8 WAS USED IN MISSION 3681 FLOWN ON 1 AUGUST 1963,
PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

- A. THE RESOLUTION IS GOOD AND THE EXPOSURE IS ADEQUATE.
- B. 9R SIDE: CREASES ASSOCIATED WITH A MANUFACTURING SPLICE
ON FRAME 1576 CONTINUE THROUGH 1607.
- C. 9L SIDE: INBOARD EDGE STATIC AND OUTBOARD EDGE FOG

Declassification Review by NGA/DoD

~~SECRET~~

OCCUR INTERMITTENTLY THROUGHOUT THE MISSION. FINE EMULSION SCRATCHES, PARALLEL TO THE FILM EDGES AND AT ERRATIC INTERVALS, APPEAR ON FRAME 1003 THROUGH 1166.

D. AT FRAME 771 THE SHUTTER HUNG OPEN FOR THE DURATION OF TWO FRAMES. IN THE PROCESS OF TITLING THE MALFUNCTION WAS ERRONEOUSLY CONSIDERED TO HAVE BEEN ONE FRAME AND THEREFORE WAS TITLED AS SUCH. PROCESSING STREAKS PINHOLES AND EMULSION BLISTERS ARE INTERMITTENT AND MINOR THROUGHOUT THE MISSION. THERE IS A TOTAL OF 1934 FRAMES ON EACH SIDE OF THIS MISSION.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PRINTING AND PROCESSING ARE GOOD AND PI SUITABILITY IS GOOD.

B. CLOUDS OBSCURE OR IMPAIR APPROXIMATELY 15 PERCENT OF THIS MISSION.

END OF MESSAGE

1